PAGE: 1 PRINT DATE: 11/29/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 03-1-0410 -X

SUBSYSTEM NAME: MAIN PROPULSION

REVISION: 1 02/20/01

PART DATA

PART NAME PART NUMBER
VENDOR NAME VENDOR NUMBER

LRU: TRANSDUCER, PRESSURE, LO2: MC449-0164-0001

BOEING

LRU: TRANSDUCER, PRESSURE, LH2 MC449-0164-0002

BOEING

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

TRANSDUCER, DIFFERENTIAL PRESSURE, LH2 (MT50) AND LO2 (MT44). THE DIFFERENTIAL PRESSURE TRANSDUCER IS NO LONGER SUPPORTED AND IS DELETED FROM OV-105 AND SUBS.

REFERENCE DESIGNATORS: MT44

MT50

QUANTITY OF LIKE ITEMS: 2

FUNCTION:

THE TRANSDUCERS WITH THEIR SIGNAL CONDITIONERS PROVIDE A MEANS OF SENSING THE PROPELLANT LEVEL IN THE ET LH2 AND LO2 TANKS BETWEEN THE POINT SENSORS IN THE BOTTOM AND THE TOP OF THE TANKS. THE SYSTEM SENSES DIFFERENTIAL PRESSURE BETWEEN THE ORBITER 17-INCH FEEDLINES AND THE GH2/GO2 ORBITER 2-INCH PRESSURIZATION LINES. THEY ARE USED TO PROVIDE GROSS INDICATION OF PROPELLANT LEVEL IN THE TANKS DURING PROPELLANT LOADING. THEY HAVE NO INFLIGHT FUNCTION. THIS SYSTEM IS ELECTRICALLY POWERED BUT PRESENTLY IT IS NOT ACTIVELY USED, AND IS NOT INSTALLED ON OV-105.

PAGE 2 PRINT DATE: 12/11/01

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 03-1-0410-04

REVISION#: 1 02/20/01

SUBSYSTEM NAME: MAIN PROPULSION

LRU: TRANSDUCER, PRESSURE, LH2/LO2 CRITICALITY OF THIS ITEM NAME: TRANSDUCER, PRESSURE, LH2/LO2 FAILURE MODE: 1/1

FAILURE MODE:

RUPTURE/LEAKAGE (EXTERNAL) OF ASSEMBLY.

MISSION PHASE: PL PRE-LAUNCH

LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA

103 DISCOVERY104 ATLANTIS

CAUSE:

FATIGUE, MATERIALS DEFECT, WELD FAILURE

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) N/A

B) N/A

C) N/A

PASS/FAIL RATIONALE:

A)

B)

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

FAILURE RESULTS IN LEAKAGE OF GHE AND/OR PROPELLANT INTO THE AFT COMPARTMENT. POSSIBLE LOSS OF CRITICAL ADJACENT COMPONENTS DUE TO CRYOGENIC EXPOSURE. POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND FIRE/EXPLOSION HAZARD. LEAKAGE DURING LOADING IS DETECTABLE USING HAZARDOUS GAS DETECTION SYSTEM (HGDS). PRELAUNCH GN2 PURGE OF THE AFT COMPARTMENT MAY LOWER THE GO2/GH2 CONCENTRATION BUT FIRE/EXPLOSION HAZARD MAY STILL BE PRESENT.

PAGE: 3 PRINT DATE: 12/11/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0410-04

DURING MANIFOLD REPRESSURIZATION, POSSIBLE LOSS OF GHE SUPPLY, RESULTING IN LOSS OF AFT COMPARTMENT PURGE.

(B) INTERFACING SUBSYSTEM(S):

SAME AS A.

(C) MISSION:

ON GROUND, VIOLATION OF HGDS LCC WILL RESULT IN LAUNCH SCRUB.

(D) CREW, VEHICLE, AND ELEMENT(S):

POSSIBLE LOSS OF CREW/VEHICLE.

(E) FUNCTIONAL CRITICALITY EFFECTS:

NONE.

-DISPOSITION RATIONALE-

(A) DESIGN:

THE TRANSDUCER UTILIZES THE VARIABLE RELUCTANCE PRINCIPLE FOR SENSING PRESSURE. IT CONTAINS A DIAPHRAGM WHICH IS EB WELDED IN AN ASSEMBLY WITH TWO 304 CRES BACKUP PLATES. INCORPORATED WITHIN EACH BACKUP PLATE ARE INDUCTANCE COILS AND TEMPERATURE COMPENSATING CIRCUITS. PRESSURE TRANSMITTING CAPILLARY TUBES ARE FURNACE BRAZED TO THE BACKUP PLATES AND TERMINATE IN DYNATUBE FITTINGS FOR SYSTEM HOOKUP. THE CAPILLARY TUBE IS MADE FROM 321 CRES, 0.094 INCH OD; 0.028 INCH WALL THICKNESS. INCORPORATED INTO EACH BACKUP PLATE IS AN 0.015 INCH DIAMETER ORIFICE TO RESTRICT GAS FLOW THROUGH A FAILED DIAPHRAGM. THE DIAPHRAGM ASSEMBLY IS MOUNTED IN A HOUSING WHICH CONTAINS TWO COVER PLATES AND AN ELECTRICAL CONNECTOR.

THE DIAPHRAGM IS WELDED TO THE BACKUP PLATES. AN ANALYSIS PERFORMED BY THE MANUFACTURER INDICATED THE WELD SAFETY FACTOR AT 745 PSID MAXIMUM OPERATING PRESSURE (EQUIVALENT TO 109% POWER LEVEL) TO BE 2.11 YIELD AND 5.27 ULTIMATE. STRUCTURAL ANALYSIS INDICATES POSITIVE MARGINS OF SAFETY FOR ALL CONDITIONS OF TRANSDUCER OPERATIONS.

RUPTURE OF THE INTERNAL PRESSURE ASSEMBLY MAY BE CONTAINED BY THE OUTER HOUSING AND COVERS, WHICH ARE SEALED WITH EPOXY. TESTS WITH AMBIENT GAS HAVE VERIFIED THAT THE HOUSING WILL HOLD PRESSURE UP TO APPROXIMATELY 200 PSI AT WHICH POINT THE COVERS DISTORT AND ALLOW LEAKAGE TO OCCUR.

(B) TEST:

PAGE: 4 PRINT DATE: 12/11/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0410-04

ATP

EXAMINATION OF PRODUCT

LEAKAGE (TRANSDUCER DIAPHRAGM ASSEMBLY ONLY)

PRESSURIZATION LINE SIDE - 600 PSID FEEDLINE SIDE (LO2) - 220 PSID FEEDLINE SIDE (LH2) - 55 PSID

PERFORMANCE (SIGNAL CONDITIONER AND TRANSDUCER)

CURRENT CONSUMPTION

REVERSE VOLTAGE OPERATION

OUTPUT SIGNAL IMPEDANCE AND NOISE

SYSTEM LINEARITY, HYSTERESIS AND REPEATABILITY (OVER TRANSDUCER PRESSURE AND TEMPERATURE EXTREMES)

SIGNAL CONDITIONER MEMORY VERIFICATION

PROOF PRESSURE (TRANSDUCER)

PRESSURIZATION LINE SIDE - 600 PSID

FEEDLINE SIDE (LO2) - 220 PSID

FEEDLINE SIDE (LH2) - 55 PSID

POST TEST PERFORMANCE VERIFICATION.

ELECTRICAL CHARACTERISTICS

INSULATION RESISTANCE

DIELECTRIC STRENGTH

VIBRATION

RANDOM - 30 SECONDS PER AXIS AT AMBIENT CONDITIONS

THERMAL CYCLE (SIGNAL CONDITIONER ONLY)

+70 DEG F TO -45 DEG F TO +145 DEG F TO -45 DEG F TO +70 DEG F.

CERTIFICATION (2 UNITS)

VIBRATION (AT AMBIENT CONDITIONS)

RANDOM - 48 MINUTES IN EACH OF 3 AXES

TRANSIENT - (5 TO 35 HZ) IN EACH OF 3 AXES

QAVT (QUALIFICATION - ACCEPTANCE VIBRATION TEST)
RANDOM - 25 MINUTES IN EACH OF 3 AXES

LEAKAGE (TRANSDUCER DIAPHRAGM ASSEMBLY ONLY)

PRESSURIZATION LINE SIDE - 600 PSID

FEEDLINE SIDE (LO2) - 220 PSID

FEEDLINE SIDE (LH2) - 55 PSID

SHOCK (MIL-STD-810)

DESIGN

PAGE: 5 PRINT DATE: 12/11/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0410-04

BENCH

EXPLOSIVE ATMOSPHERE (MIL-STD-810 WITH BUTANE)

BURST (TRANSDUCER ONLY)
PRESSURIZATION LINE SIDE - 1200 PSIG
FEEDLINE SIDE - 440 PSIG
PERFORM LEAKAGE TEST

OMRSD

ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

RECEIVING INSPECTION

INCOMING PARTS ARE VISUALLY INSPECTED FOR MATERIAL AND PROCESS CERTIFICATION.

CONTAMINATION CONTROL

CLEANLINESS LEVELS OF TRANSDUCER SURFACES ARE VERIFIED; 800A IN CONTACT WITH OXYGEN, 400 IN CONTACT WITH HYDROGEN. EXTERNAL SURFACES MAINTAINED TO VISIBLE CLEAN LEVEL ARE VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

CLEANLINESS OF SENSOR PARTS PRIOR TO ASSEMBLY IS INSPECTED. DIMENSIONS AND SURFACE FINISHES ARE VERIFIED BY INSPECTION. TORQUE APPLIED TO BASE PLATE IS CHECKED TO REQUIREMENT. ALUMINUM BASES AND HOUSINGS FINISHED WITH CHEM FILM FOR ELECTRICAL BONDING APPLICATION ARE VERIFIED. ALIGNMENT AND SEALING WITH EPOXY BETWEEN ADAPTER FITTINGS AND COVERS ARE VISUALLY EXAMINED. MANDATORY INSPECTION POINTS ARE INCLUDED IN THE ASSEMBLY PROCEDURE.

CRITICAL PROCESSES

EB WELDING OF THE DIAPHRAGM ASSEMBLY WITH THE ASSEMBLY AT REDUCED TEMPERATURE (-130 DEG F) IS VERIFIED IN ACCORDANCE WITH APPLICABLE REQUIREMENT. ALL SOLDERING AREAS OF ELECTRONIC CONNECTIONS ARE INSPECTED PER REQUIREMENT. CONFORMAL COATING CONDUCTED ON TERMINAL BOARDS WITH SOLITHANE 115 TYPE II IS EXAMINED. BRAZING CONDUCTED ON ASSEMBLY IS VERIFIED BY INSPECTION. BLACK ANODIZED EXTERNAL SURFACES AND MOUNTING HOLES OF BASE PLATES ARE INSPECTED PER REQUIREMENTS. EPOXY BONDING OF LOOSE WIRES IS VERIFIED.

NONDESTRUCTIVE EVALUATION

RADIOGRAPHIC INSPECTION OF BRAZES AND WELDS IS VERIFIED. HELIUM LEAK DETECTION IS PERFORMED TO DETECT ANY POSSIBLE LEAKAGE IN THE ASSEMBLY.

TESTING

ATP, INCLUDING PROOF PRESSURE TEST, IS VERIFIED BY INSPECTION.

HANDLING/PACKAGING

PACKAGING PER DOCUMENTED INSTRUCTIONS IS VERIFIED. SHOCK AND CONTAMINATION PREVENTION DURING HANDLING/SHIPPING/PACKAGING BETWEEN STATIONS IS MONITORED.

PAGE: 6 PRINT DATE: 12/11/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0410-04

(D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURE, FLIGHT FAILURE, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

(E) OPERATIONAL USE:

FLIGHT: NO CREW ACTION CAN BE TAKEN.

GROUND: GROUND OPERATIONS SAFING PROCEDURES CONTAIN SAFING SEQUENCE OF EVENTS FOR MAJOR LEAKS IN THE PROPELLANT SYSTEMS.

- APPROVALS -

: W.P. MUSTY S&R ENGINEERING : /S/ W. P. MUSTY

S&R ENGINEERING ITM : P. A. STENGER-NGUYEN : /S/ P. A. STENGER-NGUYEN

: /S/ HERB WOLFSON DESIGN ENGINEERING : HERB WOLFSON

MPS SUBSYSTEM MGR. : TIM REITH : /S/ TIM REITH

INSTRUMENTATION

: /S/ N/A : /S/ JEFF MUSLER : /S/ MIKE SNYDER : /S/ SUZANNE LITTLE MOD : JEFF MUSLER : MIKE SNYDER : SUZANNE LITTLE USA SAM USA ORBITER ELEMENT : /S/ ERICH BASS NASA SR&QA : ERICH BASS